

20 AUG 1958

Received from Chief Ship Surveyor

SHIP'S NAME "TURID" REPORT Abg. No. 17095  
AR.

Outstanding Conditions of Class: Subject to indented shell plate No.14 in 1st strake below main sheer etc. (p.s) being examined and dealt with as necessary next drydocking.

ACTION IS DEFERRED for drydocking.

Endorsement of Certificate ~~(As before)~~ None)

Nature of Present Survey: ~~(As before)~~ in dry dock)

Docking; W & T repairs; damage (cause not stated) involving No.4 shell plate in 1st below sheer (p.s.f).

Recommendation: SUBMITTED record of 'DS 7,58' be assigned as recommended, SUBJECT to indented shell plates Nos. 4 & 14 in 1st strake below sheer (p.s.f) being examined and dealt with as necessary next Special Survey.

DS 7,58. Subject. Amended.



*78*  
*8-8-58*  
2020  
Lloyd's Register  
Foundation