

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of LONDON

No. in Reg. Book 6786 on the Wood, Iron or Steel Sc. K. Beryl II Date, First Survey 1914 Last Survey 1914

TONNAGE: GROSS 248 Built at Selby Owners Cash & Sons By whom Cochrane & Sons, Ld. Managers ... Owners' Address ... Port belonging to Sydney N.S.W.

Surveyed Afloat or in Dry Dock? WB=CellDBorDBa Name of Dock ... Destined Voyage ... Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined. If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 12121 Port Syd (Periodical surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

CHARACTER.	Year Assigned	Year Expired	Machinery and Boilers Surveys (including date of N.B., if any)
+100 A.I. 7/31			+LMC 7.29
Stm. Trawler 3H			BS 9.30
S.S. Syd. No. 3. 7.29			T.S.C.L. 7.29

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	DK. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (state if on Felt) When put on, Month Year
Decks	State if Tanks now tested	Engine Room Skylights	Boats
Caulking of Decks	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Coamings	Ceiling	Scuppers	Condition, how ascertained (state if wedges removed)
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Outside Plating	Rudder	Hatches	Equipment letter
Breasthooks	Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Transoms	Windlass	Caulking ditto	Cables (State if now ranged)
Frames	Have Pumps now been examined and found efficient?	Treenails ditto	length (on board) size
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stimson ditto	Eule length size
Longitudinals	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Floors		Ditto ditto at other places ditto	
Keelsons		Stringers, Clamps & Shelves ditto	
Stringers		Salting ditto (state if examined.)	
Inner Bottom Plating			

General Observations, Opinion as to Class, Recommendation, &c.:— State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute Withdraw Class insert 14/9 Surveyor to Lloyd's Register of Shipping General Committee Thursday 24th September 1931 Classing Committee's decision confirmed

If so, is the Report sent now, or when will it be sent? Has a Survey also been held on the Machinery of the Ship?

A Certificate required. If so, to be sent to