

Surveyors.....

Received from Chief Surveyors.....

E "THE COUNTESS" REPORT Grk. No. 25233

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR.~~

which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Docking..... When due.....

NOTED.

Subject to buckled keelplate No.3 from aft and set in shell plating (p.s.f.) being dealt with by next Special Survey and to 30 fathoms of chain cable being supplied at the earliest opportunity.

54 P.Gl. Subject.

SPK
14.10.54.



© 2020

Lloyd's Register
Foundation

003223-003232-0101