

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

FOUNDED 1760

RE-CONSTITUTED 1834

## Certificate of Class

*Steel Screw Steamer* " *Adherity* "  
Official Number *168798* Port of Registry *London*  
Owners *F. T. Everard & Sons Limited*  
Builders, and where and when built *Spangemouth Dockyard Co. Limited, Spangemouth, 1942.*

### REGISTERED PARTICULARS.

Length	<i>123.0</i>	feet	Tonnage, Gross	<i>780</i>
Breadth	<i>30.7</i>	feet	Ditto under Deck	<i>538</i>
Depth	<i>14.1</i>	feet	Ditto Net	<i>363</i>

This is to Certify that this Ship has been surveyed by the Surveyors to this Society, and was reported to be, <sup>in</sup> ~~on the~~ *November & December, 1951*, at *Genoa & Greenhithe* in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of dry and perishable or other approved Cargoes, and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character **100A1** *Carrying Petroleum in Bulk.*

FITTED FOR OIL FUEL — FLASH POINT ABOVE 150°F.

subject to Periodical Surveys as required by the Rules. (See Endorsements Overleaf)

*Longitudinal Framing at Deck*

*Specially Surveyed London, 12.51*

Witness my hand,

*L. E. Blument*

Secretary,


*R. A. A. A.*

Chairman.

71, Fenchurch Street, London, E.C.3. *25<sup>th</sup> March, 1952*

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register  
Foundation

*Stability*

ENDORSEMENTS.

*The following items relating to the condition of this ship have been noted, but do not affect the maintenance of Classification.*

*Shell plates B5+6, C5+6 (port side) indented.*



© 2020

Lloyd's Register  
Foundation