

# LLOYD'S REGISTER OF SHIPPING

FOUNDED 1780

RE-CONSTITUTED 1834

## Certificate of Class

Steamer "EMPIRE SHEARWATER"  
Official Number 187500 Port of Registry Dover  
Owners Ministry of Transport & Civil Aviation (European Ferries Ltd., Managers)  
Builders, and where and when built William Pickersgill & Sons Ltd., Sunderland, 1945.

REGISTERED TONNAGES		MOULDED DIMENSIONS	
Gross	4285.07	Length	322' 0"
Net	2417.46	Breadth	54' 0"
		Depth	27' 0"

This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 3rd December, 1958 in a fit and efficient condition as is prescribed by the Society's Rules and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character \*100A1

Shell and weather decks to be specially examined annually. For service U.K. & Eire (excluding the West Coast of Ireland), also to and from the Baltic and Mediterranean subject to Periodical Surveys as required by the Rules. For Carriage of Non-perishable cargoes

Specially Surveyed Glasgow 12.58.

The approved minimum freeboards from the deck line are as follows:—

Tropical	-	feet	-	inches (T).	Winter	}	-	feet	-	inches (WNA).
Summer	16	feet	6½	inches (S).	North Atlantic	}				
Winter	16	feet	9	inches (W).	Allowance for fresh water for all freeboards	}	2½			inches

Witness my hand,

W. J. Ferguson  
Secretary.


Herbert A. Bell  
Chairman.

71, Fenchurch Street, London, E.C.3. 4th February, 1959.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors or other Officers or Agents of the Society."



Lloyd's Register  
Foundation





© 2020

Lloyd's Register  
Foundation

003245-003251-0143