

Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates Yes Are the Discharge Pipes above

SS "Kiruna"

It is submitted that
this vessel is eligible for
THE RECORD. + LMC. 3.21 FD

Rel

29/4/21

ACK

© 2020

Lloyd's Register
Foundation

003263-003274-0111

Can each boiler be worked separately Yes Area of fire grate in each boiler 12.2 sq ft No. of
each boiler 2 spring loaded Area of each valve 12.2 sq in Pressure to which they are adjusted 190 lbs per sq in

150 - 18" 0

$$\begin{array}{r} 2 \\ \hline 5 \overline{) 301 \ 16 \ 0} \\ \underline{60 \ 7 \ 2} \end{array}$$

$$\begin{array}{r} 2 \\ \hline 3 \overline{) 120 \ 14 \ 4} \\ \underline{112 \ 4 \ 9} \end{array}$$



Copyright © 2020

189 Lloyd's Register
Foundation