


COPY

LLOYD'S REGISTER OF SHIPPING



Port Liverpool.

6th January, 1958.

This is to Certify that ~~I~~^{we} have

Port, Centre & Starboard Boilers
Surveyed the ~~Machinery~~^{Machinery} of the "KING EDGAR" 7084 gross tons
of London as the vessel lay afloat at Liverpool on the 16th
December, 1958 & subsequently,
and that ~~I~~^{we} will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
~~us~~^{us} in connection therewith have been carried out to ~~our~~^{our} satisfaction; also
that ~~I~~^{we} will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book

M.B.S. 12,58 (now)

and that her Machinery Classification Record be continued in the Book.
subject to the fuel tank remote control valves being re-examined
and tested by the end of March, 1959 (3 months limit)

Parts now examined:

(C.S. Items only)

D. McColville

(D. McColville) (for self & colleague). Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 50m,3,58 (MADE AND PRINTED IN ENGLAND.)

003275-003281-0127