



ITEMS EXAMINED AND CONDITION FOUND, ETC.		
IN DRYDOCK Outside shell, Sternframe & Rudder		
Bunkers - coal		
Striking plates		
Chain locker & Cable holdfasts		
Equipment letter		
Anchors, No. of		
Cables (State if now ranged)		
Length on board	Fathoms	Mean diameter.
Rule length	Fathoms	Diameter.

It should be stated whether it was considered necessary to test any tanks at this time.

TANKS	EXAMINED	TESTED	CONDITION
O.F. Tanks.			
Double bottom tanks.			
Feed water & F.W. tanks.			

Indocking Date

Was it considered necessary to drill the plating at this time?

General Notes on Survey, not included above. Examination of structure in way of D.B. tanks (condition of class).

NOW DONE:- The double bottom tanks in way of the hold spaces examined internally and the solid and bracket floors, tank top plating etc. found badly buckled and rivetted connections slack - no repairs have been carried out or are contemplated in the near future. It is therefore recommended that this defective internal structure in way of the D.B. tanks be dealt with as necessary before the vessel is again placed into service.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:-

ANCHORS.

Number of Certificate.	Anchors.	WEIGHT EX. STOCK.		TEST PER CERTIFICATE.		WEIGHT REQUIRED BY RULE.		Description of Anchor.	Makers.	Where and when tested and Surveyor.
		lb.	lb.	lb.	lb.	lb.	lb.			

CHAIN CABLES.

Number of Certificate.	Length and size supplied.		Test per Certificate.		WEIGHT OF CHAIN CABLE.		Length and size per rule.		Description.	Makers of Cables.	Where and when tested and Surveyor.
	Length.	Diam.	Statutory.	Breaking.	Supplied.	Per Rule.	Length.	Diam.			

Stream Chain or Wire



© 2020

Lloyd's Register Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.