

# MONTREAL OFFICE

Name:-

"KEYDON"

Report No. Mtl. 11923

Nature of Survey:-

DAMAGE SURVEY

Damage stated caused by grounding on the 23rd September, 1957.

The following remains to complete the survey:-

Bottom shell plating in way of the fore peak (port and starboard) and No. 2 D. B. tank (p.s.) with internals in way to be dealt with as found necessary by the next drydocking.

Recommendations:-

The Vessel appears eligible to remain as classed <sup>with</sup> without fresh record of Survey, subject as previously and as above.

Amend S.R.L.

November 28th, 1957.

003275-003281-0160