

Ship's name "CUACO"

Port N.Ns.

No. 8598

GB Class is subject to wasted shell plating in bilge strake (s.s) Last survey date 4.4.63.
in way of after overboard discharge being specially examined
and dealt with as necessary by the S.S. to set up keel and
bottom plating etc.(s.s) being specially examined and dealt
with as necessary next drydocking also to a bower anchor
being supplied at the earliest opportunity.
ACTION is DEFERRED for S.S. by 6,63.

S.R.L. Appendix (as before ~~or none~~)

Surveys due SPECIAL SURVEY (C) due 3,62. Postponement until 6,63
approved 5.2.63 following a satisfactory G.E.

Nature of present survey (afloat ~~and in drydock~~)

Permanent repairs to stevedore damage.

Is interim certificate in order

Yes/No ~~xxxxxx~~

Items outstanding if any for SS

ALL ITEMS.

SS proposed to be completed by 6,63.

~~xxxxxxxxxxxxxx~~

N O T E D.

SUBJECT as above,
ACTION is DEFERRED for S.S. by 6,63.

SUBJECT

IN S.R.L. APPENDIX.

Bottom and inner bottom plating stiffened
with minor corrugations unfaired.
Shell plates in 3rd and 4th strakes
below sheer indented (p.s.f).

OFFICE NOTE

Bottom and inner bottom plating stiffened -
Mdb.5,53 with minor corrugations unfaired.

© 2020

Lloyd's Register
Foundation