

For the information of Surveyors and the Committee only.

Received at

Office

19

Lloyd's Register of Shipping.

(Report on Vessel No. 6978 Port Gothenburg)

No. 4506 SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by Messrs AB Lindholm - Notala of Notala Turkstad for the Vessel No. 6978 ^{repaired} ~~being built~~ by Messrs AB Götaverken of Gothenburg have been inspected by me as set forth below and found to be, so far as can be seen, sound & free from defects

1 rudder arm

Forgings or Castings.

Lloyd's

No. 4506

G.A. 11. 10. 27

Gothenburg 11th October 1927

G. Sander

	STERN FRAME. <u>1 Rudder arm</u>	RUDDER FRAME.	STEM.
Material	<u>S.M. Steel</u>		
Mode	<u>Forged</u>		
Material	<u>Yes</u>		
Condition	<u>Forged & finished</u>		
When Inspected	<u>1/10/27, 11/10/27</u>		
CASTINGS.			
on Standard Test Pieces.			
Test—	<u>51.3</u>		
per square inch	<u>26.0</u>		
Extension per cent.			
ending Test—	<u>180° good</u>		
before fracture	<u>✓</u>		
Test—	<u>✓</u>		
at from ground ...			
Spring Test—			
made according to Rules	<u>✓</u>		
and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

(if any chargeable) £

To be paid at

of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

0033 07-003310-0173



© 2020

Lloyd's Register
Foundation

MBT 11 27

DATE