

S.S. "MATHURA".

All air pipes provided with efficient closing appliances.

Minor repairs effected to ventilators on casing top, skylight glasses fitted in Engine skylight, hatch covers fitted in Bridge tween deck and main cargo hatchways.


New fidley door fastening fitted on starboard side in the bridge space.

-----000-----

[Signature]

30th January 1933.

*Above particulars noted
On report*



© 2020

Lloyd's Register
Foundation

003311-003320-0095