

REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

Date of writing Report 6-6- 1961 When handed in at Local Office 6-6- 1961 Port of Toronto

No. in Survey held at Toronto Date, First Survey and Last Survey 10-4- 1961
 Reg. Book (No. of Visits 1)

52978 on the Steel S.S. "AVONDALE"

TONNAGE:— Built at Sld. By whom Swan, Hunter & Wigham Richardson When 1929
 GROSS 1938 Owners Reoch Transports Limited

NET 1158 Managers - Port belonging to Montreal

Surveyed Afloat or in Dry Dock? Afloat Name of Dock _____

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 4018 Port 7/6

REPAIRS, OR EXAMINATION AS PER RULE FOR

LAKE Annual SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. + for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
BS* Great Lakes & River St. Lawrence Service	MBS* ES 4/58 M 2/60 CL 1/58 SPS 12/56
Lake SS 4/58	
AS 4/60	
DS 1/58	

	ITEMS EXAMINED AND CONDITION FOUND, ETC.		
Holds including bulkheads, inner bottom plating, etc.	Good		
Bilges & ceiling.	-do-		
Tween decks.	-do-		
Deck & deck erections.	-do-		
Machinery Space.	-do-		
Under Engines & Boilers.	-do-		
Masts, Rigging & Outfit.	-do-		
Windlass & Hawse Pipes.	-do-		
Air & Sounding Pipes with closing appliances.	-do-		
Pumps and Pumping arrangements outside machinery space.	-do-		
Steering arrangements including gear.	-do-		
W.T. Doors & Sluice valves.	-do-		
Ventilator coamings with their closing appliances.	-do-		
Hatchway coamings with their closing appliances.	-do-		
Casings, companionways and their closing appliances.	-do-		
Superstructure bulkheads with their closing appliances.	-do-		
Guard rails & freeing ports.	-do-		
Overboard discharges, also ash chutes & other shell openings.	-do-		
	EXAMINED	TESTED	CONDITION
Peaks	Yes	No	Good
Side Tanks in hold.	/	/	
Deep Tanks			
Cargo Tanks			
Cofferdams (Tankers)			
Pump Rooms			
Has a Load Line Annual Survey been held?	(Canadian Government Load Line)		
Has a Grain Survey been held?	Yes		
Has a Damage Survey been held?	No		

General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4.54" or "to remain as classed and to have record of docking, I,54 and the notation Lake S.S. 4.54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 4/61

Survey Fee Cl. & Gr. \$ 66.00
U.S.S.A. \$ 4.00
 Special Damage or Repair Fee (if any) \$ _____
 Travelling Expenses \$ 5.00
 Second Surveyor's Fee (if any) \$ _____

Fees applied for,
JUN 27 1961

THURSDAY 27 JUL 1961

Committee's Minute AS 4.61
 Character Assigned MBS. 4.61

Surveyor to Lloyd's Register
 T.L. Millar



© 2020

Lloyd's Register
 Foundation

003311-003320-0265