

79 AUG 1937

nt to Chief Surveyors _____

Received from Chief Surveyors _____

ESSEL'S NAME "SAURIAN" Report Lon. No. 103400a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey _____

When due _____

The Boiler Survey became due on this vessel 6,37.

The Grimsby Surveyors now forward a letter from the Owners requesting the withdrawal of this vessel from the Society's classification.

It is submitted the class of the vessel be withdrawn and three dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class
Insert ...

gfd
9-8-37
Sum



© 2020

Lloyd's Register
Foundation

003321-003327-0021