

COPY

Ship's name

THE PRESIDENT

Port

GNK.

No.

27200

Class is subject to

NIL.

Last survey date

5.12.12.

Docking

Propeller & inlet sea suction examined also parts of main & aux machinery for suspected damage alleged to have been sustained due to grounding.

Before repairs could be dealt with vessel was taken in tow to Troon for scrapping by the new owners, Messrs Arnott, Young, Shipbreakers.

It is submitted this information is for the guidance of the Committee.



© 2020

Lloyd's Register
Foundation

003321-003327-0218