

5.1
5c.10.40.

Lithgows Ltd.,
Port Glasgow.

Yard No.974

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME s.s "TRIONA" Report Grk. No. 22226

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey First Entry When due

This ship is of the same dimensions as the "Y" type standard vessels and the scantlings are, as in these vessels, suitable for a draught of 18" in excess of that corresponding to the freeboard which could be assigned as a C.S.S. vessel, but the arrangements have been altered to suit the Owners' special service. (See C.S.S. Dpt. endorsement 3.3.43 attached).

The tank top plating has been increased in thickness under the hatchways in lieu of ceiling.

100A1 "With freeboard"

2 Dks

Cell DB 363' 1209t, tanks at sides of tunnel 378t, wing tanks fwd 400t, FPT 173t, APT 233t

FK, 7BH (Coll to W dk, 6 to 2nd dk) 5 divisional W.T. BHs in 'tween decks Cem., Lloyd's A & CP

F 52'

O.L. 462.8'

E.S.D.

a†


The class is assigned and maintained upon the understanding that the equipment will be made to accord with the requirements of the Rules when the present state of emergency has passed, and that cargo battens will be fitted at the first available opportunity.

Insert in S.R.L:- (A bower anchor and 45 fathoms of chain cable to be supplied.) Cargo battens to be fitted at the first opportunity.

*Static
Load*

*Yes.
20.3.43*

A copy of the C.S.S. Dept.'s endorsement of the 3rd instant should be forwarded to the Surveyors and they should be requested to state whether ^{all} recommendations ~~therein~~ therein have ~~been~~ been carried out.



f.c.d. bth
21.3.43.



© 2021

Lloyd's Register
Foundation

00334-003348-0011