

18th March, 1960

SINGAPORE.

13770, 78, 85, 87, 92, 804 - As recommended.

13793 - As recommended.

13807 "STATE OF MADRAS" - As recommended, except that the class has been continued subject as previously recorded.

13799 "CITY OF COLOMBO" - As recommended, except that a record of DBS 11,59 has now been assigned.

13779 "SUKAMANDI" - As recommended, except that the condition of class recommended by you has not been imposed in this instance. The Rule length of chain cable for this ship is 75 fathoms and it is noted from your report that there are at present 120 fathoms on board.

In the circumstances I shall be glad if you will issue an amended Interim Certificate without reference to the subject of 15 fathoms of chain cable.

13784 "TARIA" - As recommended, except that the class has been continued subject to the main engine thrust block casting being examined by November, 1960. In this connection I have to inform you that the Certificate issued by the Kobe Surveyors on the 8th December, 1959 recommended that the main engine thrust block casting should be re-examined by November, 1960, but in view of the examination now carried out, I shall be glad if you will state whether this item can now be deleted from the Special Reasons List.

13789 "CARDIGANSHIRE" - As recommended. I shall be glad if you will forward a copy of your Interim Certificate in respect of this survey.



© 2021 /cont'd.....

Lloyd's Register  
Foundation

003341-003348-0041