

COPY

LLOYD'S REGISTER OF SHIPPING



Port SANTOS (Brazil)

14th November, 1961.

This is to Certify that I have
Surveyed the Machinery of the M.V. "ROSCOE", 6334 tons gross
of Liverpool, whilst afloat at Santos on the 10th November,
1961 and subsequently, on account of damage and repairs to
Nº 2 unit of Main Engine,
and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will **Recommend** that in the case of this Vessel the following
Survey Records be ~~made~~ ^{retained} in the Supplement to the Register Book
as now recorded,

and that her Machinery Classification Record be continued in the Book.

Subject to Nº 2 unit of the Main Engine to be re-aligned
and piston and rod refitted at a U.K. port where the vessel
bound, before the end of December, 1961. Subject to all other
Parts now examined: conditions, at present attached to the
(C.S. Items only) ship's class by the Society's Surveyors,
being dealt with as previously recommended.

(C.A. Davies).

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."