

Memo. respecting incomplete survey on
the "EMPIRE BARON"

London 27th January 1942

The Owners hope to complete the outstanding items
of the Special Survey at this time.

Freeboard conditions: - (1) Vent. coamings on forecastle dk. (56")
are being specially supported by brackets, 1 on poop dk. is
protected by house, (2) gauges to air pipes are being renewed
as required, (3) bolted plates on shell are being made
watertight.

Washbasin discharges amidships are from appliances
situated on or above bridge dk.

Arthur M. Smith
Surveyor.

FOR { MR. HILL.
MR. NETTLETON.

Lois submitted and
copy be forwarded to
the Hon. Surgeons for issue
when the port of registration has been
inserted. The 2nd. No. 1 completed
and they showed be endorsed for
deeper loading when the conditions
have been complied with

Lois
27/1/22



© 2020

Lloyd's Register
Foundation