

16 JUL 1959

Received from Chief Ship Surveyor

SHIP'S NAME "STARAS" REPORT Bgk. No. 2245
VC

Outstanding Conditions of Class: SUBJECT to buckled ship side and forecastle deck plating (s.s.) being specially examined and dealt with as found necessary next drydocking.

S.R.L. — Appendix. (~~As before~~ or None)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Examination and temporary repairs to foremast.

Recommendation: SUBJECT as above, and to foremast being specially examined and dealt with as found necessary on arrival in Japan.

As now. SUBJECT.

Blk (new)



© 2020
J. J. J. J.
16/7/59

Lloyd's Register
Foundation

003369-063276-0103