

129 JUL 1932

s.s. "CONFIDENZA"

London 97751a.


The class is subject to the donkey boiler not being used until it has been examined and satisfactorily reported upon, and to some indented plating on the starboard side being dealt with at the Owners' convenience.

The Genoa Surveyors now forward a copy of a letter received from the Owners, from which it appears that for economical reasons they have decided to withdraw the vessel from class.

IT IS SUBMITTED the vessel's class be withdrawn from the Register Book, and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...


29.7.32

© 2020

Lloyd's Register
Foundation

003371-003384-0025