

2 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

"PAUA".

Rpt.

H. Kg.

No.

8513.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)


Survey ~~COMPLETION OF~~ SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 3

MS
This Survey / due 6,39 now held
DBS " 9,39 ~~partly~~

now

completed, and the following repairs carried out (due to wear and tear):-
Propeller renewed; repairs effected to pumps, electric wiring etc.

It is submitted the vessel is eligible to remain as classed, with
notation of ~~LMC 1,40,~~
~~DBS 1,40,~~
~~SL 1,40~~
11.39
as recommended.



© 2020
7.3.40.

Lloyd's Register
Foundation

003385-003390-0076