

Has the **Automatic Governor** been tested and found efficient when the whole load is suddenly thrown on or off *Yes*
Generators, do they comply with the requirements regarding overload *Yes*, are they compound wound *Yes*
Mr. Munro
Please enter following information in
Electric F.E. Rep: on M.V. "Pana" 1412 tons.
A 6 KW dynamo driven by a Ruston & Prosser
oil engine fitted 3.42 for degaussing
purposes.
L.F.
28/5/62.
© 2020
Lloyd's Register
Foundation
003385-003390-0101
woodwork or other combustible material, state distance of same horizontally from or vertically above the switchboards
is all insulation of high dielectric