

17th December, 1954.

47 As recommended.

"STRATHALBYN" The contents of your report have been noted. The Committee, at their meeting today, gave instructions for notation of "Sunk - now refloated and repairing" to be deleted from the Register Book and the class of the ship to be qualified with notation "Class suspended pending Special Survey" and repairs. Owners' agents should be informed accordingly.



© 2020

Lloyd's Register  
Foundation

003391-003400-0092