

41

3m. 10.47.

1

Messrs. Yarrow & Co.Ltd., Glasgow.

Yard No. 2089.

Sister Ship "DIRECTOR"

CLASS CONFIRMED

 $11/4/57$

Sent to Chief Surveyors.

Received from Chief Surveyors.

GB Diesel Electric Paddle &
VESSEL'S NAME Salvage Tug "DEXTEROUS"

REPORT Gls. No. 86638

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey.

FIRST ENTRY

XXXXXXXXXXXX

L. 145'-0"

B. 30'-0"

D. 15'-0"

The scantlings and arrangements, as reported, conform with the Society's Revised Rules and Regulations, and are in accordance with or equivalent to those shown on the approved plans.

*100A1 "For Towing & Salvage Services"
DS 12,56

1 dk; pt E.W.

DB in mchy space O.F; Side & DTs pt W.B. 6t pt O.F;

DTsf pt O.F. pt F.W; APT 9t.

6BH; LACP.

O.L. 157'-3"

Extreme breadth: 60'-0"

Rise of floor: 4"

ESD

 $1\frac{1}{8}''$

RSP 2/10/57

NOTED FOR POSTING 3/26/77

Equipment letter for Fees (D 3303) = "h"



R.S.D.

9.4.57.

© 2020

Lloyd's Register
Foundation

003401-003408-0040