

2c.11.30.

1E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Sarakan

Rpt.

Rot.

No.

19959

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

oil engines 2 S.C.A.

If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of

approved type

Yes
No.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ LURE 11.30

SB 7/11.

It is concluded that the Donkey Boiler safety valves are fitted with easing gear but this should be confirmed.

Lr 9.1.31

P. 11



© 2020

Lloyd's Register
Foundation

003401-003408-0091

It is submitted the Surveyors be requested to forward a plan of the

003401-003408-0093