

Has a Load Line
Survey been held? **yes - LLRS**

Freeboard Marks verified **yes**

COPY

Ship's name **IRINIS BLESSING**

Port **Venice**

No. **0830**

Last survey date **24/3/63**

Class is subject to

- ① Outboard auxiliary engine crankcase (repaired 7.61) being re-examined by 3.63.
- ② Inboard auxiliary engine crankcase (repaired 7.61) being re-examined by 3.63.
- ③ Starboard windlass cable lifter bush being renewed and shaft examined by 3.63.
- ④ Starboard M/E cylinder cover nos 1, 3 & 4 and port M/E cylinder cover nos 1, 3, 4, 5 & 6 (EW 5.62) being re-examined by 11.63.
- ⑤ Temporary repairs to no 182 starboard main engine exhaust manifold being specially examined & dealt with by 3.63

Docking W/D 4.5 m.t.m.

General Examination

The Surveyor reports general examination effected & 3R items 1-5 not dealt with at this time.

C.S. Advanced.

It is submitted that this vessel is eligible to remain as **CLASSED**, until 31st May 1963, subject as all items above

9/5/63



© 2020

Lloyd's Register
Foundation