


Bel 10530

It is concluded that the thicknesses of the end plates of these Air Receivers are as approved and not as reported but this should be confirmed.

L1/1/31



© 2020

Lloyd's Register  
Foundation

003429-003433-0032

Material { back.....

Tensile strength { .....

Thickness { .....

..... piece of stay tu

(stay