

Lloyd's Register of Shipping.



FOUNDED 1780.

RE-CONSTITUTED 1834.

Certificate of Class

Steel Screw Motorship "King Alfred" *ex "Empire Ray"*
 Official Number 167003 Port of Registry London
 Owners King Line, Limited (Dodd Thomson & Co., Limited Managers)
 Builders, and where and when built Greenock Dockyard Co., Limited, Greenock, 1941.

REGISTERED PARTICULARS.

Length <u>432.2</u> feet	Tonnage, Gross <u>6919</u>
Breadth <u>56.2</u> feet	Ditto under Deck <u>6461</u>
Depth <u>33.2</u> feet	Ditto Net <u>4151</u>

This is to Certify that this Ship has been surveyed by the Surveyors to this Society, and was reported to be, on the 3rd July, 1947 at Cardiff & in November 1948 at Glasgow in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of dry and perishable or other approved Cargoes, and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character 100A1 Specially Surveyed Cardiff-7.47 with freeboard

subject to Periodical Surveys as required by the Rules, *to indented shell plating etc (s.s.), shell plate F8 (p.s.) & fire damage to deep tank bulkhead & deck (p.s.) being dealt with at the first convenient opportunity; to buckled plating & stiffening of bulkhead between Nos. 1 & 2 holds being dealt with at the first opportunity & to 45 fathoms of chain cable being supplied at the end of the present emergency.*

THE FREEBOARDS FROM THE DECK LINE ARE AS FOLLOWS —

Tropical <u>10</u> feet <u>1 1/2</u> inches (T).	Winter North Atlantic } <u>9</u> feet <u>9</u> inches (WNA).
Summer <u>10</u> feet <u>8</u> inches (S).	Allowance for fresh water for all freeboards } <u>7</u> inches
Winter <u>11</u> feet <u>2 1/2</u> inches (W).	

Witness my hand,

P. Clement

Secretary.

R. Smith

Chairman.

71, Fenchurch Street, LONDON, 13th December 1949

N.B.—If the ship herein named proceed to sea with a less freeboard than that assigned, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2020

Lloyd's Register
Foundation

003429-003433-0190