

MEMORANDUM

2 MAY 1963

m: **LLOYD'S REGISTER OF SHIPPING,**

71, FENCHURCH STREET,  
LONDON, E.C.3.

(Ref. R.)

The Surveyor(s) at HONG KONG

Date: 25th April, 1963

el's Name: S.S. "JOHORE BAHRU"

JMC/EP

QUESTION

ANSWER

With reference to my  
ter of the 29th March, I shall be  
l to learn how this case now stands  
arding the supply of equipment.

I shall also be glad to  
n if you are in a position to  
me know what arrangements have  
made for the Special Survey  
e held by the end of July as  
ed.

Date:—

29th April, 1963.

Owners state that they  
have not yet been able to obtain  
suitable second hand cable and  
are reluctant to order the  
equipment new in view of the  
uncertainty regarding the ship's  
future. Nor has any definite  
decision yet been made regarding  
the Special Survey, which becomes  
due in July next.



© 2020

Lloyd's Register  
Foundation

003434-003443-0018

SR

This 150 ftm. of chain cable has  
been outstanding since 8.62 and the  
sewers should be informed that unless  
definite arrangements are made for the replacement  
of the cable by the due date of the S.S. the class of the  
ship may be jeopardized.

RWT  
6/6/63

Ji.  
25.63