

EA

Ship's name

"JOHORE BAHRU"

Port

SNG

No.

1633

Last survey date 5.3.63.

Class is subject to fractured shell plate G.9 (s.s. from aft) and G.10 (s.s.a) being specially examined and dealt with as necessary next drydocking, to keel plate No.14 and A.15 (p.s. from aft) being specially examined and dealt with by the S.S., to 150 fathoms of chain cable being renewed at the earliest opportunity and to fractured shell plates F.8 and G.8 (p.s.f) being dealt with as necessary by 6,63. ACTION is DEFERRED for S.S. by 7,63, also for

S.R.L. Appendix (as before ~~xxxxxx~~) a short time for Equipment.

Surveys due

SPECIAL SURVEY (C) due 7,62. Postponement until 7,63 approved 12.10.62.

Nature of present survey (afloat and ~~in drydock~~)

Damage repairs - heavy weather.

Is interim certificate in order

Yes/No *Yes*

Items outstanding if any for SS

ALL ITEMS.

SS proposed to be completed by

Recommendation

(doubled)
SUBJECT as above and to fractured shell plate (1 p.s.) (2 s.s.) in way of F.P. tank being specially examined and dealt with as necessary by the Special Survey, but ACTION continue to be DEFERRED for S.S. by 7,63 and for a short time for Equipment.

SUBJECT

~~IN S.R.L. APPENDIX.~~

~~Indents in shell plates (p & s).~~

C.S.S. Records Dept.
to note.



© 2020

Lloyd's Register
Foundation

003434-003443-0023