

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
                          { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

## ENCLOSURE

12th October, 1962.

C  
WK/HJW  
Dear Sirs,

### CLASSING LETTER

10579 "LEERSUM" - As recommended and subject as previously recorded with regard to the propeller being examined at the next drydocking.

10800 "JOHORE BAHU" - As recommended. It is concluded that the mean diameter of chain cable on board is reported as 1.25/32" (renewal size) refers only to 150 fathoms recommended for renewal, and that the diameter of the other 120 fathoms is above that size, but your confirmation is desired.

Please forward a sketch showing details of the screwshaft where the crack was removed, as stated in your Report No.9345.

"JESSIE MAERSK" 10826 - As recommended, a notation of CS. 8,62 having been assigned, and assignment of the notation SS. 8,62 has been deferred pending the renewal of 135 fathoms of worn chain cable.

A certificate respecting the machinery is now enclosed.

Yours faithfully,

pro. Clerk to the  
Classification Committee.

The Surveyors,  
KOBE



Lloyd's Register  
Foundation

003434-003443-0028