

29th May, 1956.

NTWERP

1115, 99, 217. As recommended.

1057. "CATO". As recommended, except that a record of screwshaft examination 2,56 has been assigned. In this connection I have to point out that the recommended date to be assigned should be the date on which the screwshaft was examined (Refer Circular 1598). I shall be glad if you will issue an amended Cert. B.1.

139. "KYLEQUEEN". As recommended. No mention is made in the report or plans of the fitting of a ten gallon fire extinguisher or of the steam supply to the transfer pumps, and I shall be glad to learn whether these matters are in order.

C. 31242. As recommended.



© 2020

Lloyd's Register  
Foundation

003434-003443-0315