

SEA. KING

Submitted Halifax N.S. Surveyor
furnished with C. 11. Ibo. Rpt.,
typical F. E. Reports, also copy
Circular. of 23rd May 46. and enclosure
(attached), and advised that
he should be guided by Circulars
1891. in this case. His attention
should also be drawn to. Circ. 1890.
and also to 1888 especially applicable
to this type of ship

Forward attached ~~note~~ sheets relating to the
engines pumping arrangements *Sh.*
5/7/48

4/6/51 the attached copy of a Rpt. 13
for a typical EC2-5.61 vessel
engine ~~business~~ installation might
also be forwarded.

X R G
L

Lloyd's Register
Foundation
5/7/48

003490 - 003451 - 0215