

COPY

LLOYD'S REGISTER OF SHIPPING



Port of Stockholm,

28th January, 1958.

This is to Certify that I have

Surveyed the steel single screw steamer "RUNMARÖ", 2887 tons gross of Stockholm, on the 27th and 28th December, 1957, whilst the vessel was lying on slipway at Oskarshamn, for Docking and General Examination with a view of Postponement of Class,

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, also that I will

Recommend that she be continued as now classed (viz. +100A1) with fresh record of Docking Survey 12.57, subject to the General Examination being completed, the recommended repairs being carried out and the forecastle shell plating etc. (port side) being dealt with before the vessel be placed in service (now laid up at Oskarshamn) and to all other conditions at present attached to the vessel's class being dealt with as previously recommended, she

being fit to carry her usual cargoes.

To complete the General Examination, the steering gear, hatch covers in place and Nos. 2 and 5 D.B. tanks in the vicinity of the machinery be examined and following repairs carried out: 60 frames in holds to be partly renewed, shell plates Nos. C 2 and D 18 (port and starboard) be renewed and tunnel and A.P. tank top plating be repaired.

I.W. Lager.

Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BiS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	SS(P)	Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."