

7 SEP 1960

Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

NAME "SPETSAI GLORY" REPORT Pir. No. 8579

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

"Surveys Overdue 6,59" is recorded in the Register Book.

The class is subject to indented shell plating etc. (p.s.f) being dealt with before ship leaves Piraeus.

The ship also requires to be examined in dry dock after grounding also for repairs before she leaves Piraeus.

There is an S.R.L.Appendix Note.

The PIRAEUS Surveyors report (7,60), ship examined in dry dock preparatory to proceeding to Toulon (for breaking up) in tow as an unclassified ship.

IT IS SUBMITTED ACTION be DEFERRED pending receipt of further information.

IN S.R.L. )  
IN S.R.L. APPENDIX ) to be amended as necessary later.

*CBM*  
6.9.60



© 2020

Lloyd's Register Foundation

003487-003494-0084