

back plate Steel Thickness $\frac{13}{16}$ Greatest pitch of stays $16 \times 8\frac{1}{2}$ Working pressure of plate by


R 279 Made by Q Mar Eng Works
Stock

Hpl Report No. 15896

It is submitted that further action in the case is unnecessary ~~as~~ until this boiler is ~~not intended~~ fitted on a classed vessel.

Date

Entered in "Unclassed" Boiler Book.



Bell 2020

3/8/31

3/8/31

Lloyd's Register
Foundation

003487-003494-0126