

THROUGH AMSTERDAM

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

6th February, 1962.

C
MWK/EMD

Dear Sirs,

Motorship "JAVA"

This ship was surveyed at Calcutta during December/January when the tubes of the starboard exhaust gas economiser were found defective.

It was recommended that the starboard exhaust gas heated economiser heating coils be examined and dealt with before the end of July, 1962 and the Committee have continued the class subject to this matter receiving attention by the time stated.

The class is also subject to the following items receiving attention:-

- (1) Port exhaust gas economiser not to be used until surveyed.
- (2) Port Main Engine scavenge pump lower piston and rod to be examined by August, 1962.
- (3) Windlass main drive gear to be examined by September, 1962.

In order to complete the Donkey Boiler Survey, which became due at the end of May, 1961, the condition of class regarding the starboard exhaust gas economiser requires to be dealt with.

Yours faithfully,

c.c. Amsterdam

Deputy Clerk to the
Classification Committee.

Messrs. N. V. Stoomvaart Maatschappij "Nederland",
P.O.Box 1100,
AMSTERDAM,
Holland.

Lloyd's Register
Foundation

003525-003532-0028