

the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the
distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully on the ...

MONTREAL OFFICE

PICTON

Report No. Mt1. 12902


of Survey:-

MBS

owing remains to complete the survey:- Complete

Recommendations:-

The Vessel appears eligible to remain as classed (with ^{with}~~without~~) fresh record of MBS 2,59.


August 6th, 1959.




Lloyd's Register
Foundation

003525-003532-0125