

- 2 OCT 1941

31944

Lloyd's Register of Shipping.

Ship's Name "PORT FREMANTEE".

Official No. 149807.

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines
in _____

Additional accommodation has been fitted in vicinity of tonnage space:-

A steel companionway has been fitted on tonnage opening - 6'-0" x 3'-0" x 6'-6" high
with coaming 24" above wood deck. (war)

2 portlights with deadlights of substantial construction fitted p. & s.

A W.C. has been fitted in tween decks (P.S.) with storm valve and additional
screw down non-return valve operated from above freeboard deck.

Washbasins have been fitted in tween decks (S.S.) with storm valve & additional
gate valve operated from second deck (See Report 10).

Meat ports (pos.) in lower tween decks have been permanently closed (war)

W. Robinson 9/11

SURVEYOR TO LLOYD'S REGISTER.

Copy placed on board vessel.

(war)