

Received from Chief Ship Surveyor.....

10 AUG 1962

S NAME "STANVAC RIAU" REPORT SNG No. 15713

EA

Standing Conditions of Class:

SUBJECT to shell plates C.1 (p & s.a) being specially examined and dealt with as necessary by the Special Survey, and to keel plates Nos.4,5,6,7 & 9 also 10 and shell plates A.4,7, & 11 (p.s) from aft being specially examined and dealt with as necessary at the next drydocking.

Appendix. (~~As before~~ None)

Result of Present Survey: (Afloat and in dry dock)

Docking: Examination with a view to ascertaining repairs required for the Special Survey due 11,62
Wear and tear repairs.

Recommendation:

SUBMITTED record of DS 5,62 be assigned,
subject as above.

DS 5,62 Subject.

OFFICE NOTE

See Research Dept. memo of 22.1.62 regarding the drilling of this ship.
also plans forwarded with Sng letter 30/6/62.



S.P.H.
20/7/62
© 2020

Lloyd's Register
Foundation

003549-003555-0171