

subject to

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

F-3 JUL 1961

NAME.....

Paisio

REPORT.....

Helwig

No. 8151

A.b.o. due 2/61 partly held 2/61 now advanced.

The Surveyor reports the furnaces of the forward boiler deformed and recommends boiler not to be used until there have been deat with.

It is submitted that this vessel is eligible for THE RECORD A.b.o. 2/61 when the survey has been completed.



complete. A.b.o. Repair to fwd boiler furnace to be carried out & its safety valves adjusted under steam.

Lloyd's Register
Foundation