

COPY

LLOYD'S REGISTER OF SHIPPING



14. JUN. 1961

Port Helsingfors,

24th of May, 1961.

139/61

This is to Certify *that I have*

Surveyed the Machinery of the M.T. "PANSIO" at Uleåborg, 17-19. 5.61, in so far as the forward Boiler was now surveyed and the safety valves of the ps and ss Boilers adjusted under steam and oil burning and steamsmothering remote controls tried, and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

DBS 2/61 when the Boiler survey has been completed,

and that her Machinery Classification Record be continued in the Book. To complete the Boiler Survey the deformed furnaces of the Forward Boiler to be dealt with.

I recommend that the forward Boiler not be used before said repair has been carried out.

arts now examined:

(G.S. Items only)

A. Weber.

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steam Pipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B.1.) 150m,5,60 (MADE AND PRINTED IN ENGLAND)

003572-003580-0045