

COPY.

United with the British Corporation Register.

Lloyd's Register of Shipping.



--:EMOD WOV

Port. LONDON

4th November, 1958.

This is to Certify that I have

time

surveyed the Boiler and machinery of the M.V. "LATIRUS" 6476 tons
 of London, on the 30th October, 1958 and subsequently, whilst
 the vessel was afloat at anchorage in the River Blackwater, for
 the purpose of ascertaining the general condition of the machinery
 for a contemplated voyage to Rotterdam and the return voyage to
 the River Blackwater as an unclassified vessel,

and that I have transmitted to the Committee of Lloyd's Register

of Shipping, London, a Report, as on the other side, stating

that all repairs recommended by me have been completed to

my satisfaction.

B. This vessel has notation in the Register Book of
 "Laid up - Special Survey and Repairs incomplete."

signed: T.A. ORDE,

Surveyor to Lloyd's Register.

p.p P.H.W. EVANS

certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
 the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to
 be noted that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for
 any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of
 the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other
 agents of the Society."

003581-003590-0123

Lloyd's Register
Foundation

COPY.

Lloyd's Register of Shipping

United with the British Corporation Register.

NOW DONE:-

The main engine tested working and manouevring at the anchor.
Windlass tested working.
Steering gear tested working.
Donkey Boiler examined under steam.
Electrical circuits megger tested.
Auxiliary machinery generally examined externally.

The machinery as now seen is considered to be in satisfactory general condition for the purpose referred to overleaf.

Port Nos. 3 & 8

Centre Nos. 5 & 3

Starboard Nos. 3 & 5

This is to Certify that I have

A Freeboard Renewal Survey has been carried out at this time with a view to the issue of a new Certificate of Fitness for the vessel. The vessel was surveyed on the 30th October, 1958 and subsequently, whilst the vessel was at anchor in the River Blackwater, for the purpose of ascertaining the general condition of the machinery for a contemplated voyage to Rotterdam and the return voyage to the River Blackwater as an unclassified vessel.

and that I have transmitted to the Committee of Lloyd's Register

of Shipping, London, a Report, as on the other side, stating

that all repairs recommended by me have been completed to

my satisfaction.

This vessel has notation in the Register Book of "Laid up - Special Survey and Repairs incomplete."

signed: T.A. ORDE,

Surveyor to Lloyd's Register.

P.P. P.H.W. EVANS

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
The Committee of the Society has their best endeavours to ensure that the functions of the Society are properly executed, it is to be held responsible for any error or omission in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error or omission in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society.

Lloyd's Register
Foundation