


RD REPORT on the

S.S. "Aberdeen"


It is submitted the Surveyor be informed that to make the hatchways equivalent to the rule requirements an $8 \times 3\frac{1}{2} \times \frac{1}{2}$ " channel bar or two $3\frac{1}{2} \times 3\frac{1}{2} \times \frac{1}{2}$ " angles should be fitted on the lower edge of all webs in Nos 2, 3 & 4 hatchways thus.



G.M.

W.D.

26.9.18



© 2020

Lloyd's Register
Foundation

003599-003604-0212