

COPY

# LLOYD'S REGISTER OF SHIPPING

BELONGS TO  
ROTTERDAM REPORT NO. 51530

Part of ROTTERDAM.

12th May, 1961.

*This is to Certify that I have*

*Surveyed the Machinery of the m.s. "PARWASSOS", 9968 tons gross of  
Piraeus, whilst placed in drydock and lying afloat at this port on the  
15th March, 1961 and subsequent dates for Condition, C.S. Completion, S.S.  
I.S. and Wear and Tear Repairs.*

*and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me in connection therewith have been carried out to my satisfaction; also  
that I will Recommend that in the case of this Vessel the following  
Survey Records be made in the Supplement to the Register Book  
C.S. (with date) when completed, S.S. 8-60 as previously recommended,  
and I.S. new 3-61 C.S.*

*and that her Machinery Classification Record be continued in the Book  
subject to the inboard and centre furnaces of the starboard boiler  
being specially examined at next Annual Boiler Survey due 8-61, without  
the condition of class relating to the starboard screwshaft.*

Parts now examined: (C.S. Items only)

Lubricating oil pumps of both main engines.  
Propellers and outside fastenings.

*E. M. Dudock*


Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

E. M. Dudock.

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,  
it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held  
responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book  
published by the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof,  
Surveyors, or other Officers or Agents of the Society."



003599-003604-0334