

25th July, 1962.

MUTTA

49 "JALAGOVIND" - As recommended.

I acknowledge receipt of your letter of the 18th July, the contents of which have been noted.

51 "JAG MATA" - As recommended, except that with regard to the machinery the class has been continued subject to the windlass at gypsy shaft main bearing pedestal and clutch support being repaired at the next drydocking as recommended in your .20632.



© 2020

Lloyd's Register
Foundation

003605-003610-0088