

"PARKWOOD" - Hpl. Rpt.No. 19813

Before this case receives consideration
IT IS SUBMITTED the Surveyors be requested to
furnish the thicknesses of deck plating as
ascertained by drilling and as required for a
Survey (D), also to confirm that the cement in way
of bottom plating has been found adhering
satisfactorily and that it was not necessary to drill
same.

*See letter
24-7-57*
Apr 23/7

[Signature]
11-7-57



© 2021

Lloyd's Register
Foundation

003620-003624-0188