

2 MAY 1958

REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

Date of writing Report 22nd April, 1958 When handed in at Local Office..... 19... Port of MONTREAL
 No. in Reg. Book 23818 Survey held at Montreal Date, First Survey and Last Survey 19th April, 1958
 (No. of Visits 1)

23818 on the Steel S.S. "PAUL MANION"
 TONNAGE:— Built at Wallsend By whom Swan, Hunter & Wigham Richardson Limited When 1929 year month
 GROSS 1927 Owners Colonial Steamships Limited.
 UNDER DK Managers R. Scott Misener Port belonging to Sarnia
 NET 1147

Surveyed Afloat or in Dry Dock? Afloat Name of Dock..... Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 11980 Port MTL

REPAIRS, OR EXAMINATION AS PER RULE FOR LAKE ANNUAL SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. + for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
BS* Great Lakes & River St.	4,56
Lawrence Service.	MBS 3,57
Lake S.S. 4,56	TS 4,56
A.S. 4,57	SPS 12,56
D.S. 4,56	

	ITEMS EXAMINED AND CONDITION FOUND, ETC.
Holds including bulkheads, inner bottom plating, etc.	Good
Bilges & ceiling.	- do -
Tween decks.	-
Deck & deck erections.	Good
Machinery Space.	- do -
Under Engines & Boilers.	- do -
Masts, Rigging & Outfit.	- do -
Windlass & Hawse Pipes.	- do -
Air & Sounding Pipes with closing appliances.	- do -
Pumps and Pumping arrangements outside machinery space.	- do -
Steering arrangements including gear.	- do -
W.T. Doors & Sluice valves.	- do -
Ventilator coamings with their closing appliances.	- do -
Hatchway coamings with their closing appliances.	- do -
Casings, companionways and their closing appliances.	- do -
Superstructure bulkheads with their closing appliances.	- do -
Guard rails & freeing ports.	- do -
Overboard discharges, also ash chutes & other shell openings.	- do -

	EXAMINED	TESTED	CONDITION
Peaks	Yes	No	
Side Tanks in hold.			
Deep Tanks			
Cargo Tanks			
Cofferdams (Tankers)			
Pump Rooms			
Has a Load Line Annual Renewal Survey been held?	No	(C. G. Load Line)	
Has a Grain Survey been held?	Yes		
Has a Damage Survey been held?	No		

General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4,54" or "to remain as classed and to have record of docking, I,54 and the notation Lake S.S. 4,54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 4,58

Survey Fee \$ 66.00
 Special Damage or Repair Fee (if any) USSA \$ 4.00
 Travelling Expenses \$ 5.00
 Second Surveyor's Fee (if any) \$

Fees applied for, APR 23 1958

A. K. McDougall
 Surveyor to Lloyd's Register of Shipping.
 (A. K. McDOUGALL)

Committee's Minute THURSDAY 15 MAY 1958

THURSDAY - 6 JUL 1961

Character Assigned AS 4,58 MBS 2,58

Laid up pending survey

Noted for Header

Noted for Header



© 2020

Lloyd's Register Foundation

003625-005630-0001

If so, is the Report sent now, or when will it be sent?

The Surveyors are requested not to write on or below the space for Committee's Minutes.