

is subject to the working Pressure of the Port Doubney boiler being reduced to
bs/sqins until the furnaces are renewed by the end of June 1959 (12 months limit)
to both screwshafts being withdrawn and the stern tubes rebushed as
may before the end of May 1959. 4E

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor. 19 SEP 1958

AME "RIZA KAPTAN"

REPORT 1ST

No. 4726


DBS due 7.5.58 partly held 6.5.58 now completed.

Safety Valves adjusted under steam & oil Burning
system examined under working conditions

It is submitted that this
vessel is eligible to remain
as CLASSED. With fresh record of:-

DBS. 6.5.58 now as previously recommended

Subject as above.



© 2020
18.9.58

Lloyd's Register
Foundation

003625-003630-0121